


TO WHOM IT MAY CONCERN

The certify that:-

1. The school building of Kendriya Vidyalaya, No. 1, Air Force Station (AFS), Jorhat – 785005 (Assam) has been personally inspected on dated 21/05/2021 at 10:30 am.
2. The Vidyalaya building and other structures has been thoroughly checked and is found that Office building (A), Class Room(B) , Laboratory (C), Class Room (D), and Staff Room (E), double story building (copy attached) "the School building is strong safe & secure.


Dated: 21 May 2021


Station: Jorhat-05




(Sham Sunder Singla)
AE (Civ)
AGE B/R-II (AF) Jorhat

COUNTERSIGNED


(Ajay Agrawal, IDSE)
EE
Garrison Engineer (AF)





- ① Class Room, office Bldg are safe (A, B, C, D, E) 
- ② Toilet Build. (F) unsafe 

KENDRIYA VIDYALAYA NO. 1 AFS JORHAT

————— To Jorhat —————>